



TSCHORN®
Mess- und Spannmittel

fractalnost.com.ua

TSCHORN® 4.0

 **Made in
Germany**



Edge finder 3D (Workpiece measurement)

fractainost.com.ua



Repeatable



cheap
cost- benefit



Placement
(flexible
processing method)



Status display
clearly visible

With the help of the edge finder, you can automatically determine your workpiece position / location and check / control the accuracy of your workpiece.

Zero setter
(Tool setting)

fractalpost.com.ua

ility +/- 3 μm

efit ratio

t of the receiver
and outside the pro-
room possible)

splay
isible to the user




With the help of the zero setter you can automatically measure tool lengths or check if the tool is broken.


The history of probing goes back over 100 years

fractalnost.com.ua

*Edge finder
mechanical*



*Edge finder
electrical*



around 1900

around 1990

ar

TSCHORN® 4.0

fractalnost.com.ua

3D Tester



ound 2000

2017

The principle of the development

based on a common electrical edge finder
with LED



fractalnost.com.ua

**Step 1:
Removing
the LED**

**Step 2:
Installing a radio
electronics**



TSCHORN® 4.0

was born



www.fractalnost.com.ua

Please note: In this catalogue, TSCHORN 4.0 is presented using the example of the Siemens control. TSCHORN 4.0 also works on any other commercially available machine controller, provided that the control has measuring cycles included.

fractalnost.com.ua

The functionality:

1. Probing signal = electrical contact (between shank & ball)
2. LED lights up in RED
3. At this moment, the probing signal is sent to the receiver
4. The receiver receives the signal
5. The receiver forwards the signal via cable to the machine control



Machine control



Connecting to the machine


Your machine has to meet the following requirements:

1. The machine has to have so called measuring cycles
2. You need a power supply between 12V and 24V DC
3. You need an input for the probing signal
4. You need an input for the error signal



(Please note: the error signal is not mandatory)

fracta1nost.com.ua


You only have to connect 4 wires with the machine control:




Electrical power supply:



fractaInost.com.ua



Probing signal



Error signal



Important note:

Work on the machine control should only be undertaken by specially trained qualified personnel.


Again, the example „Siemens“ was used. However, the connection is possible on any available machine control, provided that it has measuring cycles.

Examples of use


Probing edge in manual mode:

1. Position the probe manually in front of the edge.
2. Start the probing process.
3. The machine starts the axis movement.
4. During the movement, the control waits for the probing signal.
5. The workpiece is touched (= electrical circuit closed).
6. The probing signal is sent to the control.
7. The axis movement is stopped.
8. The actual position is written into the offset (the zero offset).
9. The tester moves to safety distance.

fractalnost.com.ua



X axis



Y axis




Z axis

Probing circle in manual mode:

1. Manually position the probe near the centre of the edge.
2. Enter the circle diameter and, if necessary, the measuring depth (incrementell).
3. Start the probing process.
4. The machine independently measures 4 points and determines the circle centre.
5. The circle center (X / Y) is written into the offset.
6. The tester moves to the centre of the circle.



Bore hole



Spindle

Align by edge or level




fractaInost.com.ua

1. Position the tester manually before point 1.
2. Start: Point 1 is measured and the tester moves to safety distance.
3. Position the tester manually before point 2.
4. Start: Point 2 is measured and the tester moves to safety distance.
5. The control calculates the angle for the coordinate rotation.
6. The angle for coordinate rotation is automatically written into the offset.

Align by level

1. Position the tester manually before point 1.
2. Start: Point 1 is measured and the tester moves to safety distance.
3. Position the tester manually before point 2.
4. Start: Point 2 is measured and the tester moves to safety distance.
5. Position the tester manually before point 3.
6. Start: Point 3 is measured and the tester moves to safety distance.
7. The control calculates the angle for the coordinate rotation.
8. The angle for coordinate rotation is automatically written into the offset.



Sample applications

Measurements in automatic mode

Measurements can be integrated directly into the machining program by means of measuring cycles. Programmable measurements of various kinds are possible and open up a variety of manufacturing possibilities.

fractalnost.com.ua



Bore hole



reference circle



Spindle



reference circle



Rectangular pocket




Rectangle



Nut



Root face



Corner
outside



Corner
inside



Align
by edge



Align
by level

Processing the measured values




Transfer to offset

Example: You clamp your workpiece but want to check the exact position of each workpiece and adjust the machining.

This allows you to transfer the results directly to your zero offset in programmable mode.

Transfer to tool offset

Example: You mill a precise fitting bore. While processing, you can check the bore and the correction value is automatically passed to the tool offset.



Output in Excel file

Example: You check every workpiece during machining. The measured values can then be output to a file.


Decide good / bad

Example: You measure each workpiece during machining. If the measurement result is within the tolerance, the machine continues to work. If the measurement result is out of tolerance, the machine is automatically stopped.



Dimensions

fractalnost.com.ua



Complete system

The complete system contains:

- Edge finder 3D (for workpiece measurement)
- Zero setter (for tool setting)
- Receiver
- With test certificate



Art.- No.	Description	Price / pc.
00SYS1020	System TSCHORN 4.0 edge finder 3D + zero setter	2.590,00 €

Workpiece measurement - edge finder 3D



The system contains:

- Edge finder 3D (for workpiece measurement)
- Receiver
- With test certificate

fractalnost.com.ua



Art.- No.	Description	Price / pc.
00SYSOKT0	System TSCHORN 4.0 - edge finder 3D	1.950,00 €

Tool setting - zero setter

The system contains:

- Zero setter (for tool setting)
- Receiver
- With test certificate



Art.- No.	Description	Price / pc.
00SYSONE0	System TSCHORN 4.0 - zero setter	1.570,00 €



TSCHORN®
Mess- und Spannmittel

fractalnost.com.ua



ФРАКТАЛЬНІСТЬ

представництво в Україні:

ТОВ "ФРАКТАЛЬНІСТЬ"

Наші контакти:

вул. Машинобудівна, 46, 03067, Київ

тел.: +38 044 227-57-73

факс: +38 044 394-80-94

e-mail: office@fractalnost.com.ua

www.fractalnost.com.ua

TSCHORN® 4.0

 **Made in
Germany**